## DB-2 (page 1of4) Report No.: **Customer Name** Test Instrument Seaward Primetest 100 **Debs Sweet Delights** (PAT Testing Service) 28/05/2019 Date: 7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX. **Dave Brazier Test** Visual Test Class: I,II,III. Ext'n lead IEC lead Insulation Leakage **Function** Date of Inspect € Bond ID No. Appliance Description Appliance Location Comments RPE Riso Leakage Check Pass or **Next Test** Pass or Ohms Mohms mΑ Fail Fail 001 Item not found IEC Lead 1M **IEC** 13 0.04 19.99 28/05/2020 002 **Pass Pass Pass** 003 IEC Lead 2.5M IEC **Pass** 13 0.05 19.99 **Pass Pass** 28/05/2020 004 Extension Lead 4M 2 Way Ext 13 0.08 19.99 **Pass** 28/05/2020 Pass Pass 005 Item not found 28/05/2020 Apple Charger Visual Inspection Only 006 Ш **Pass Pass Pass** 1.5V Charger 28/05/2020 Ш 19.99 0.10 007 **Pass** Pass **Pass** lunfused 800 Item not found Item not found 009 4 Way Ext 13 0.07 19.99 28/05/2020 010 Extension Lead 5M Pass **Pass Pass** 011 Item not found 28/05/2020 012 IEC Lead 1M **IEC** Pass 13 0.02 19.99 **Pass Pass** IEC Lead 2M **IEC** 13 0.04 19.99 28/05/2020 013 Pass **Pass Pass** 014 Item not found 28/05/2020 Extension Lead 2M 4 Way 13 0.04 19.99 015 Ext **Pass Pass Pass** 28/05/2020 016 Extension Lead 2M Ext 13 0.08 19.99 **Pass Pass** 4 Way **Pass** 017 Item not found 018 litem not found 28/05/2020 019 IEC Lead 1.5M IEC Pass 13 0.04 19.99 **Pass Pass** 020 Item not found 021 Item not found Extension Lead 5M 4 Way 28/05/2020 022 Ext 13 0.08 19.99 **Pass** Pass **Pass** 4 Way 13 28/05/2020 023 Extension Lead 5M Ext 0.09 19.99 **Pass Pass Pass** 4 Way 13 19.99 024 Extension Lead 4M Ext 0.08 **Pass Pass** 28/05/2020 **Pass** 025 Item not found

## DB-2 (page2of4) Report No.: **Customer Name** Test Instrument Seaward Primetest 100 **Debs Sweet Delights** (PAT Testing Service) 28/05/2019 Date: 7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX. **Dave Beazier** Visual Test Test Class: I,II,III. Ext'n lead lead Inspect Bond Insulation Leakage **Function** Date of 3 ID No. Appliance Description Appliance Location Comments Check **Next Test** Pass or RPE Riso **I** Leakage Pass or Fuse Ohms Mohms mΑ Fail Fail 28/05/2020 Eurolive B112 Speaker 0.12 19.99 0.51 026 **Pass Pass Pass** 28/05/2020 Eurolive B112 19.99 0.53 027 Speaker 0.08 **Pass Pass** Pass Charger 28/05/2020 028 Ш **Pass** 19.99 0.1 **Pass Pass** IEC 28/05/2020 029 IEC Lead 2.5M Pass 5 0.06 19.99 **Pass Pass** 28/05/2020 Extension Lead 10M Ext 10 0.20 19.99 030 2 Way Pass **Pass Pass** 031 Item not found 28/05/2020 032 Extension Lead 2M 4 Way Ext Pass 13 0.04 19.99 **Pass Pass** Item not found 033 13 28/05/2020 4 Way 034 Extension Lead 1M Ext **Pass** 0.05 19.99 **Pass Pass** 035 Item not found 28/05/2020 036 Charger Ш unfused Pass 19.99 0.10 **Pass Pass** 037 Item not found 038 Item not found Charger 19.99 28/05/2020 unfused 039 Ш **Pass** 0.10 **Pass Pass** 040 Item not found 041 Item not found 28/05/2020 19.99 0.10 unfused 042 Charger Ш Pass Pass **Pass** 043 Item not found 044 Item not found 13 19.99 28/05/2020 IEC Lead 2M IEC 045 **Pass** 0.11 **Pass Pass** LED Light Set 28/05/2020 046 0.09 19.99 0.33 **Pass Pass** Extension Lead 2M 4 Way Ext 13 0.05 19.99 **Pass** 28/05/2020 047 Pass **Pass** 28/05/2020 048 LED Light **Pass** 13 0.12 19.99 0.23 **Pass Pass** LED Light 13 28/05/2020 049 Pass 0.07 19.99 0.21 **Pass Pass** 050 Item not found

### DB-2 (page3of4) Report No.: **Customer Name Debs Sweet Delights** (PAT Testing Service) Test Instrument Seaward Primetest 100 28/05/2019 Date: 7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX. **Dave Beazier** Test Visual Test Class: I,II,III. Ext'n lead lead Inspect Bond Insulation Leakage **Function** Date of ID No. | Appliance Description | Appliance Location Comments Check Pass or Pass or Next Test Fuse **R**PE Riso **I** Leakage Fail Fail Ohms Mohms mA 051 Item not found 28/05/2020 052 Extension Lead 4M 2 Way Ext **Pass** 13 0.10 19.99 **Pass Pass** IEC 13 **Pass** 28/05/2020 053 IEC Lead 1M **Pass** 0.01 19.99 **Pass** 054 Item not found 055 Item not found 28/05/2020 13 19.99 056 LED Rope Light Ш **Pass** 0.10 **Pass Pass** Charger 19.99 0.10 28/05/2020 unfused 057 **Pass Pass Pass** 058 Ш **Pass** 19.99 0.10 **Pass Pass** 28/05/2020 unfused Charger 28/05/2020 059 IEC Lead 1M **IEC** 5 0.05 19.99 **Pass Pass** Pass 28/05/2020 Alesis Speaker 0.20 060 Pass 0.09 19.99 **Pass Pass** 061 Item not found 062 IEC Lead 3M **IEC** 13 0.16 19.99 28/05/2020 **Pass Pass Pass** 063 Item not found IEC Lead 4M **IEC** 13 28/05/2020 064 **Pass** 0.08 19.99 **Pass Pass** 0.10 28/05/2020 065 LED Light **Pass** 0.09 19.99 **Pass Pass** 066 LED Light **Pass** 13 0.08 19.99 0.38 **Pass Pass** 28/05/2020 28/05/2020 067 IEC Lead 1M **IEC Pass** 13 0.03 19.99 **Pass Pass** IEC Lead 2.5M **IEC** 5 0.06 19.99 28/05/2020 068 **Pass Pass Pass** IEC Lead 1M IEC 5 0.02 19.99 28/05/2020 069 **Pass Pass Pass** 0.07 0.54 28/05/2020 070 LED Light Pass 19.99 **Pass Pass** 28/05/2020 19.99 071 LED Light **Pass** 0.05 0.20 **Pass Pass** 28/05/2020 072 Charger **Pass** 19.99 0.10 **Pass Pass** unfused Apple Lead 3 28/05/2020 Visual Inspection Only 073 **Pass Pass Pass** 074 Apple Lead **Pass** 3 **Pass Pass** 28/05/2020 Visual Inspection Only Apple Power Adapter 28/05/2020 **Pass** 19.99 0.11 **Pass** Pass

## DB-2 (page4of4) **Report No.: Customer Name** Test Instrument Seaward Primetest 100 **Debs Sweet Delights** (PAT Testing Service) Date: 28/05/2019 7 Willow Drive, St Marys Bay, New Romney, Kent. TN29 0SX. **Dave Beazier** Visual Test Test Class: I,II,III. Ext'n lead lead Inspect Bond Insulation Leakage **Function** Date of ID No. | Appliance Description | Appliance Location Comments Check **Next Test** Pass or Pass or Fuse **R**PE Riso **I** Leakage Fail Ohms Fail Mohms 28/05/2020 Visual Inspection Only 076 Apple Adapter Ш **Pass** 3 **Pass Pass** IEC Lead 1M 28/05/2020 077 **IEC Pass** 13 0.03 19.99 **Pass** Pass 28/05/2020 IEC 19.99 078 IIEC Extension Lead 3M **Pass** 0.11 **Pass Pass** AC Adapter 15V 28/05/2020 Unfused 19.99 0.10 079 **Pass Pass Pass** Apple Power Adapter 28/05/2020 080 Ш **Pass** 19.99 0.10 **Pass Pass** 28/05/2020 10M 2way 081 Extension Lead Ext **Pass** 10 0.19 19.99 **Pass Pass** 40m 4way 13 0.60 19.99 28/05/2020 adjusted RPE 0.70 ohms 082 Extension Lead Ext **Pass** Pass Pass IEC Lead 2M IEC **Pass** 13 0.03 19.99 **Pass Pass** 28/05/2020 083 28/05/2020 084 X Air Mixer Desk **Pass** 0.05 19.99 0.38 **Pass Pass** 28/05/2020 AC Adapter 5V 19.99 Unfused 085 Ш **Pass** 0.10 **Pass Pass** 28/05/2020 086 Extension Lead 2M 4way Ext **Pass** 13 0.04 19.99 **Pass Pass** The items 001 to 086 were inspected and tested on the date of this report, passed the requirements of PAT testing and were deemed safe for use at the time of testing. 26 Items were not found for this report. DI Eastgate for Debs Sweet Delights (PAT Testing Service)